



LABOR RELATIONS DIVISION

401 Broadway NE
Albuquerque, NM 87102
Phone: 505-841-4400
Fax: 505-841-4424

226 South Alameda Blvd
Las Cruces, NM 88005
Phone: 575-524-6195
Fax: 575-524-6194

WWW.DWS.STATE.NM.US

1596 Pacheco St, Suite 103
Santa Fe, NM 87505
Phone: 505-827-6817
Fax: 505-827-9676

Wage Decision Approval Summary

1) Project Title: Roof modification at ECO HS 2023-2642 BH
Requested Date: 11/16/2022
Approved Date: 11/17/2022
Approved Wage Decision Number: SF-22-2834-B

Wage Decision Expiration Date for Bids: 03/17/2023

2) Physical Location of Jobsite for Project:
Job Site Address: 2301 W Zia Rd
Job Site City: Santa Fe
Job Site County: Santa Fe

3) Contracting Agency Name (Department or Bureau): Santa Fe Public Schools
Contracting Agency Contact's Name: Kristy Olivo
Contracting Agency Contact's Phone: (505) 467-3400 Ext.

4) Estimated Contract Award Date: 11/16/2022

5) Estimated total project cost: \$419,779.17
a. Are any federal funds involved?: No
b. Does this project involve a building?: Yes - This project includes an addition to the existing gym structure
c. Is this part of a larger plan for construction on or appurtenant to the property that is subject to this project?: No
d. Are there any other Public Works Wage Decisions related to this project?: No
e. What is the ultimate purpose or functional use of the construction once it is completed?: Install new wood nailers at top of exterior parapet walls. Two layers of ISO will installed at main roof areas. Installation of tapered Polysio insulation to provide drainage at Bridgeway between buildings and at vestibule roof. Installing faux coping and metal fascia and drip edge at walkway areas.

6) Classifications of Construction:

Classification Type and Cost Total	Description
General Building (B) Cost: \$419,779.17	Install new wood nailers at top of exterior parapet walls. Two layers of ISO will installed at main roof areas. Installation of tapered Polysio insulation to provide drainage at Bridgeway between buildings and at vestibule roof. Installing faux coping and metal fascia and drip edge at walkway areas.