



**LABOR RELATIONS DIVISION**

401 Broadway NE  
Albuquerque, NM 87102  
Phone: 505-841-4400  
Fax: 505-841-4424

226 South Alameda Blvd  
Las Cruces, NM 88005  
Phone: 575-524-6195  
Fax: 575-524-6194

**WWW.DWS.STATE.NM.US**

**Wage Decision Approval Summary**

1) Project Title: Aquatic Center Roof Repairs - Roofs Inc - 20250787 MAF  
Requested Date: 08/22/2024  
Approved Date: 08/23/2024  
Approved Wage Decision Number: CU-24-2784-B

**Wage Decision Expiration Date: 12/21/2024**

2) Physical Location of Jobsite for Project:  
Job Site Address: 1700 E 7th St  
Job Site City: Clovis  
Job Site County: Curry

3) Contracting Agency Name (Department or Bureau): City of Clovis  
Contracting Agency Contact's Name: LeighAnn Melancon  
Contracting Agency Contact's Phone: (575) 763-9632 Ext.

4) Estimated Contract Award Date: 08/09/2024

5) Estimated total project cost: \$1,825,153.98  
a. Are any federal funds involved?: No  
b. Does this project involve a building?: Yes - City of Clovis Aquatic Center Roof Repairs  
c. Is this part of a larger plan for construction on or appurtenant to the property that is subject to this project?: No  
d. Are there any other Public Works Wage Decisions related to this project?: No  
e. What is the ultimate purpose or functional use of the construction once it is completed?: City of Clovis Aquatic Center Roof Repairs

6) Classifications of Construction:

<b>Classification Type and Cost Total</b>	<b>Description</b>
<b>General Building (B)</b> <b>Cost: \$1,825,153.98</b>	Remove and replace existing insulated translucent 2 3" /roof and wall panels and replace with new (apx 329 panels). Detach existing high voltage from side of existing structure. Bury existing high voltage lines...saw cut concrete where applicable and pour new to finish. Remove existing insulated translucent wall panels and existing windows. Replace lower wall panels and all windows with new, low-E insulated glass. Replace upper wall panels on gable ends with new insulated translucent wall panels. Remove and replace existing insulated translucent roof panels and replace with new. Fabricate and install a new internal gutter system between the natatorium and interior building.